


REMARKS: 30' W ACCESS EASEMENT

1-2	53'x56.6' W	814.03	48-45	N40°07'16" W	33.00
2-3	53'x42.2' W	501.51	45-46	N45°08'18" W	76.11
3-4	57'x1.2' W	1.00	46-47	N45°08'18" W	20.56
4-5	57'x1.2' W	1.00	47-48	N37°02'11" W	79.75
5-6	52'x8-47' W	80.81	48-49	N37°02'11" W	72.65
6-7	54'x5-35' W	97.46	49-50	N33°28'08" W	27.45
7-8	53'x5-35' W	123.05	50-51	N32°28'08" W	94.60
8-9	53'x5-35' W	123.05			
9-10	53'x4-48' W	76.47			
10-11	57'x21.3' W	69.59			
11-12	N45°08'18" W	67.96			
12-13	N45°08'18" W	37.10			
13-14	N45°08'18" W	76.32			
14-15	N45°08'18" W	76.32			
15-16	N45°08'18" W	76.32			
16-17	N45°08'18" W	76.32			
17-18	N45°08'18" W	100.86			
18-19	N45°08'18" W	100.86			
19-20	N45°08'18" W	82.56			
20-21	N39°35'38" W	100.23			
21-22	N39°35'38" W	100.23			
22-23	N39°35'38" W	100.23			
23-24	N39°35'38" W	100.23			
24-25	N39°35'38" W	100.23			
25-26	N39°35'38" W	89.42			
26-27	N29°01'10" W	100.70			
27-28	N29°01'10" W	209.95			
28-29	N29°01'10" W	209.95			
29-30	N29°01'10" W	209.95			
30-31	N29°01'10" W	64.88			
31-32	N50°31'11" W	47.31			
32-33	N50°31'11" W	66.51			
33-34	N50°31'11" W	42.84			
34-35	N50°31'11" W	42.84			
35-36	N50°31'11" W	52.72			
36-37	N50°31'11" W	52.72			
37-38	N50°31'11" W	27.06			
38-39	N50°31'11" W	27.06			
39-40	N50°31'11" W	77.73			
40-41	N50°31'11" W	77.73			
41-42	N50°31'11" W	82.32			
42-43	N50°31'11" W	82.32			
43-44	N50°31'11" W	82.32			

NOTE: ON ALL LOT CORNERS UNLESS OTHERWISE SPECIFIED.

1. OWNER CERTIFY THAT IN ANY SECTION THIS IS A CORRECT REPRODUCTION OF THE ORIGINAL AND THAT THE SAME IS A TRUE AND CORRECT COPY OF THE ORIGINAL AND THAT THE SAME IS A TRUE AND CORRECT COPY OF THE ORIGINAL AND THAT THE SAME IS A TRUE AND CORRECT COPY OF THE ORIGINAL.



LAKE SHORE SUBDIVISION

SURVEY FOR: LINCOLN

DATE: 1-24-79

DEAN H. TEASLEY
GA REG. LAND SURVEYOR

NOTED BY: E.E.

APPROVED BY: D.T.

FILED IN: 11A

DATE: 2/1/79

Revised Oct 3, 1979
T. D. Wood, Inc